



January 18, 2026

IGAL/SECT/1-26/9

To
National Stock Exchange of India Limited
Exchange Plaza, C - 1, Block G
Bandra Kurla Complex
Bandra - (E)
Mumbai - 400 051

To
BSE Limited
Phiroze Jeejeebhoy Towers
Dalal Street
Mumbai - 400 001

Symbol: INDIGO

Scrip Code: 539448

Subject: Disclosure under Regulation 30 of SEBI (Listing Obligations and Disclosure Requirements) Regulations, 2015 ("SEBI Regulations")

Dear Sir/ Madam,

Please refer below to the details as required under Regulation 30 of SEBI Regulations in respect of orders received by the Company:

1. Name of the authority(s)	Director General of Civil Aviation (DGCA)
2. Nature and details of the action(s) taken or order(s) passed	<p>DGCA has issued 8 orders based on the findings of the Inquiry Committee constituted to review the operational disruptions between 3rd and 5th December 2025. The orders stipulate the following actions:</p> <ol style="list-style-type: none">1. Financial penalties comprising the following:<ol style="list-style-type: none">a) One-time systemic penalties of INR 1.80 crore for non-compliances under applicable Civil Aviation Requirements (CARs) and penalty for continued non-compliance with revised FDTL CAR for 68 days (from December 5, 2025 to February 10, 2026) amounting to INR 20.40 crore, aggregating to INR 22.20 crore; andb) A direction to furnish a Bank Guarantee of INR 50 crore, to be governed under the <i>IndiGo Systemic Reform Assurance Scheme (ISRAS)</i>, with phased release linked to DGCA-verified implementation of systemic reform measures.2. Caution issued to the Chief Executive Officer (CEO) for inadequate overall oversight of flight operations etc.,

InterGlobe Aviation Limited

Registered Office: Upper Ground Floor, Thapar House, Gate No. 2, Western Wing, 124 Janpath, New Delhi – 110 001, India. M +91 9650098905, F + 91 11 43513200 Email: corporate@goidigo.in

Corporate Office: Emaar Capital Tower-II, Sector-26, Sikanderpur Ghosi, MG Road, Gurugram-122002, Haryana, India. T +91 124 435 2500.

CIN no.: L62100DL2004PLC129768

goidigo.in

	<ol style="list-style-type: none"> 3. Warning issued to the Accountable Manager (Chief Operating Officer – COO) for failure to adequately assess the impact of the Winter Schedule 2025 and the revised FDTL provisions, leading to widespread operational disruptions. 4. Warning issued to the Senior Vice President – Operations Control Centre (OCC), along with directions to the company to relieve him of current operational responsibilities and not assign any accountable position. 5. Warnings issued to Deputy Head – Flight Operations, AVP – Crew Resource Planning, Director – Flight Operations, for operational, supervisory, and roster-management related lapses.
3. Date of receipt of communication from the authority	January 17, 2025
4. Details of violation(s)/contravention(s) committed or alleged to be committed	Non-adherence to the directions issued under Rule 133A of the Aircraft Rules, 1937
5. Impact on financial, operation or other activities of the listed entity, quantifiable in monetary terms to the extent possible	<p>The financial impact arising from the said orders has been detailed in point no. 2 above. From an operational standpoint, DGCA has noted that the Company restored normal operations within a short period following the December 2025 disruptions.</p> <p>Further, no additional material impact on other business activities of the Company has been communicated as part of the said orders.</p> <p>The Company is in the process of reviewing the DGCA orders and will take necessary actions as may be required.</p>

This is for your information and record.

Thanking you,
For **InterGlobe Aviation Limited**

Neerja Sharma
Company Secretary and Chief Compliance Officer