



TGV SRAAC LIMITE

6-2-1012, 2nd Floor, TGV Mansion, Khairatabad, Hyderabad - 500004, (T.S.) India.

Phone: +91-40-23313842 Fax: +91-40-23313875

E-mail: hyd2alkalies@gmail.com; hyd 2alkalies@rediffmail.com http://www.tgvgroup.com CIN: L24110AP1981PLC003077



REF:TGVSL:SECL:BSE:2025-26

October 26, 2025

BSE LIMITED, PHIROZE JEEJEEBHOY TOWERS, 25th FLOOR, DALAL STREET, MUMBAI-400 001

Phone: 022-22721233 / 34

Kind Attn: DCS - CRD

Dear Sir,

Sub: Failure of Transformer - Estimated loss of production - Reg.

Ref: 1. Regulation 30 read with Schedule III Part-A Para-B of SEBI (LODR)

Regulations, 2015. 2. Scrip Code: 507753.

%%%

With reference to the above subject, we bring to your kind notice that winding in Transformer supplied by M/s Transformers and Rectifiers India Ltd., has failed. This has resulted in production loss of about 120 TPD of caustic soda and chlorine 106 TPD. This effect may continue for about 60 days. The company is in contact with the supplier for rewinding. Company is exploring other alternatives in this regard for early restarting.

This is for your kind information and for taking the same on record please.

Thanking you,

Yours faithfully,

For TGV SRAAC Limited

(V. Radhakrishna Murthy) Chief General Manager &

Company Secretary

